FUTURE PROJECTS 2017 AND BEYOND	SCHOOL	STATUS	COMMENTS
Install exhaust fan in Nurse's bathroom	MES	In Process	Need to troubleshoot - very loud and is currently turned off
Add ceiling fans in West Gym	Both	2017	
Kiln Exhaust	Both	2017	
Life Safety - Fire Alarm Additions	Both	2017	
Begin Addition and Replacement of hand dryers	Both	Start 2017	
Reseal where the metal clerestory meets the brick & damaged drywall			
due to water leaks - Student Entrance	MMS	2017	Will check with Fanning/Howey & repair clerestory & drywall
Repair locks and door closers	MMS	2017	Vendor has been contacted
Courtyard landscaping	MMS	2017	
Add intercom access from an additional location	MMS	2017	Steve will contact vendor for pricing
Repair edge of conference room table	MES	2017	Terry has purchased material needed
Replace light covers or replace fixtures in west stairwell	MES	2017	
Install handrail by sidewalk - Northwest Corner Entrance	MES	2017	
Purchase and install Walk Pads near Chiller	MES	2017	
Create gravel storage area for winter equipment	MES	2017	
Explore problem with retention pond not working properly - Field Tiles??	MMS	2017	Steve will contact Erikkson Engineering
			Contact F/H for source of wooden guardrail - can install if we can get beam or
Replace Guardrail by playground	MMS	2017	should we get a steel guardrail
Add "Area of Refuge" signs	Both	2017	
Replace broken classroom shades	MES	2017	
Remove invasive trees from detention ponds	Both	2017	
Replace Old Boiler with 2 boilers	MES	2017 or 2018	Dependent on energy rebates
Additional security cameras if the budget allows	Both	2017 +	
Repair Life Safety items identified by Fanning-Howey	Both	ONGOING	
Explore solution to water problem at courtyard doors into the media	MES	2018	POSSIBLE AWNING? - Only occurs in driving rains depending on direction of
Replace wood on garage	MES	2018	
Explore removing lockers and moving Kindergarten cubbies into the hall	MES	FUTURE	
Playground equipment for Early Childhood	MES	FUTURE	Estimate of \$72,000 - \$108,000
Replace VCT flooring in classrooms???	MMS	FUTURE	
Explore science room renovation - Split Level addition	MES	FUTURE	Requires a significant amount of asbestos abatement.