MILLBURN C.C. SCHOOL DISTRICT #24			
4/23/2018			
FUTURE PROJECTS 2018 AND BEYOND	SCHOOL	STATUS	COMMENTS
Kiln Exhaust	Both	2018	Estimate of \$13,500
Begin add/replacement of hand dryers	Both	2018	
Remove invasive trees from detention ponds	Both	2018	
Install playground benches	Both	2018	
Explore Replacement of water heater that serves all but the kitchen in the 1999	MES	2018	
Install exhaust fan in Nurse's bathroom	MES	2018	Need to troubleshoot - very loud and is currently turned off
Add 2nd door buzzer in MES Office	MES	2018	
Repair laminate on tables/casework as needed	MES	2018	
Install handrail by sidewalk - Northwest Corner Entrance	MES	2018	
Purchase and install Walk Pads near Chiller	MES	2018	
			POSSIBLE AWNING? - Only occurs in driving rains depending on direction of wind - talk with
Explore solution to water problem at courtyard doors into the media center	MES	2018	architect
Explore sound management solutions for echo near Media Center Desk	MES	2018	
Replace soffit, facia, & siding on garage on playground	MES	2018	
Replace broken classroom shades	MES	2018	
Front island - weed, new weed barrier, and add rock	MES	2018	
Explore cost to remove asbestos floor tile in bridge area	MES	2018	
Grates over window wells - derust/paint ? just make presentable!	MES	2018	
Explore options to replace tile on cafeteria stage floor	MES	2018	Possible sheet flooring
OT/PT Room - leak - when rain blows, comes in the ceiling mounted univent	MES	2018	Needs attention prior to summer
Add No Parking signs by the drive into the back parking lot	MES	2018	Order and install prior to summer
Lower hooks in 1st Grade Lockers	MES	2018	
Hooks and Bolts atatched in rooms (lockdown)	MES	2018	
Reseal where the metal clerestory meets the brick & damaged drywall due to water	MMS	2018	
Courtyard landscaping	MMS	2018	Partially Completed
Add intercom access from an additional location	MMS	2018	
Explore problem with retention pond not working properly - Field Tiles??	MMS	2018	Steve will contact Erikkson Engineering
Add fan cut-off at MMS West Gym for ceiling fan	MMS	2018	
Troubleshoot scoreboard issues	MMS	2018	
Clock Replacements as needed	MMS	2018	
Paint Mr. Rowlands office	MMS	2018	
Explore conversion of room at MMS for use as a Maker Room	MMS	2018	
Replace bleacher seats	MMS	In Process	
Life Safety - Fire Alarm Additions	Both	2019	Est of \$69,264
Begin repair of Life Safety items identified by Fanning-Howey	Both	2019	Bid - November 2018
Replace Old Boiler with 2 boilers	MES	2019	Estimate of \$180,180
Additional security cameras if the budget allows	MES	2018	Get cost to see if feasible for 2018
Create Gravel storage area for winter equipment	MES	2018	Work with civil engineer to determine if this will create a problem with drainage
Explore removing lockers and moving Kindergarten cubbies into the hall	MES	FUTURE	
Playground equipment for Early Childhood	MES	FUTURE	Estimate of \$72,000 - \$108,000
Replace VCT flooring in classrooms	MMS	FUTURE	